Annexure D

BUILDING SAFETY CERTIFICATE

No. D40/1C

Dated: **15/11/2025.**

It is certified that the existing building **ST. JOSEPH SCHOOL** (name of the building or premises) at **Village Nikamuddinpur, Pargana Ghesua, Post- Machhalishahar, Jaunpur** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1					

The building is owned/occupied by **ST. JOSEPH SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **P.W.D. JAUNPUR** (Name of Department/ Govt.) on **10/11/2025** (date of inspection) in the presence of **Noman Khan, Jaunpur** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **15/11/2025** for a period of **1** years in accordance with rule and subject to compliance of the specific conditions as appended-

1.Na

2.Na

3.Na

4.Na

Issued on **15/11/2025** at **JAUNPUR** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : सहायक अभियन्ता निर्माण खण्ड लो0नि0विभाग जौनपुर

Designation : _____

Name & Address of Department/ Office: _____